# General Environmental Incident Summary

Incident: 2000 Notice: 7/26/2013 0000 Occurred: 7/26/2013 0000

DEM Incident No: No Further Action: ✓

Responsible Party: Bismarck State College

County: Burleigh
Twp Rng Sec Qtr: 139 80 31

Lat Long + Method: 46.82230 -100.81650 Navigation quality GPS Location Description: Behind Jack Science Building 1414 Schafer Street

Bismarck ND

Submitted By Info: Don Roethler

Received By Info:

Contact Info: Don Roethler

PO Box 5587

Bismarck ND 58506

Affected Medium: 03 - soil
Near. Occupied Bldg: 25 Feet

Type of Incident: Ethylene Glycol leeak from underground pipes

Release Contained:

Reported to NRC: Unknown

**Contaminant:** Ethylene Glycol

Volume of Release: 50 gallons

Duration of Release: 0 hours

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: Unknown

Number of Fatalities: Number of Injuries: Cause of Incident:

Had 2 underground chiller lines lose pressure. Excavated around lines and found leaking couplings on pipes.

#### Risk Evaluation:

Comtaminated soil removed

# Potential Env. Impacts:

None

### Action Taken/Planned:

Repaired lines removed comtaminated soil and hauled to city land fill spoke to Steve Tillotson at ND Health Dept about the leak

### Wastes Disposal Location:

City of Bismarck landfill per Steve Tilloston

### Other Agencies Involved:

## **Updates**

Date: 7/26/2013 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

Release impacted surrounding soils. Scott Stockdill will inspect site 7/26/2013.

Updated Volume: None at the time of this update

Date: 7/29/2013 Status: Inspection

Author: Stockdill, Scott

Notes:

N.) 46.822305 W.) -100.816491

Arrived at location 2:05pm CST 7/29/2013.

Soil removed with lines exposed. One of two leaks repaired, two more lines losing pressure. They had planned to backfill on 07/30/2013.

More follow-up required.

**Updated Volume:** None at the time of this update

Date: 7/30/2013 Status: Inspection

Author: Roberts, Kris

#### Notes:

7/30/2013 - 10:00 on location. Visited with Keith from BSC maintennance. Heating/cooling system had been losing pressure slowly for 6 months. System had been repressured with coolant at least twice in that time. Leak was found on line between building and chiller, repaired, and approximately 3 cubic yards of contaminated soil was sent to Bismarck LF. At request of NDDoH, a confirmation sample from below the leaking pipe will be collected and analyzed.

While dealing with this issue, another pressure loss was noted on the lines between the building and the cooling tower. It is not known at this time whether the leak is inside the building or outside. More follow-up is needed to determine how much has leaked from the system, and what is required for clean up.

No photos taken.

**Updated Volume:** None at the time of this update